

Connecting Steel: Verify Before Releasing the Load

Todd Jerome Jenkins | v1.0 | Reviewed October 9, 2026 | Discussion + field checks

Why this matters

A member can appear seated while its connection or temporary support is incomplete. Before the hoisting line is released, the connecting crew needs evidence for this member and this erection stage.

Objective: Identify the connection-specific release conditions and confirm who verifies them before release.

Key hazards or failure points

Wrong member or detail; incomplete connection; disturbed shared connection; missing temporary support; trapped hands; unsuitable access or fall protection.

Practical controls

- Match the member and connection to current erection information. Identify the required fasteners or engineered equivalent, temporary support and release decision before positioning.
- Use trained connectors and the access, positioning and fall protection required for their actual task. Keep hands and bodies out of trapping spaces as the member moves.
- Keep the connection and support sequence intact. Do not remove shared bolts, alter anchors or remove bracing to make the next piece fit without the applicable technical decision.

Verify It in the Field

From the planned safe work position, match the member mark and connection location to the current detail. Have the responsible person resolve missing or conflicting information.

Before release, the designated checker confirms the actual connection and required supports meet the applicable criteria. Record the detail, connection finding, checker and release communication.

Ask the connecting crew and lift personnel to repeat the release and stop arrangement. Confirm protected access remains usable through connection and rigging removal; do not test stability by releasing the line.

Stop and reassess

Hold release for uncertain connection criteria, missing fasteners or support, unexpected movement, a shared-connection conflict or lost communication. Keep clear while the lift team follows its safe stopping procedure. Resolve, recheck and rebrief before continuing.

Ask the crew

1. What must be verified before this member is released?
2. Could the next connection disturb support for the first member?
3. Who checks the connection and communicates the authorized release?

Use the task plan and required specialist decisions before exposure.

Sources: OSHA 1926.754–.756, .760–.761; actual erection details.

Free next step: [JHA/JSA planning & field-verification worksheet](#)

Expanded guidance and separate forms: toddjeromejenkins.com/toolbox-talks/connecting-structural-steel-safely